

Runways

H1: 40 x 40 (ASPH)

16/34: 6006 x 150 (ASPH-G) 09/27: 11818 x 150 (ASPH-G)

Communications

GROUND 121 9 TOWER 121 0

ATIS 124.575 (845) 567-9311 APP/DEP 132.75 (NEW YORK)

Coordinates

Latitude 41-30-14.737N Longitude 074-06-17.418W

Navigation

Flevation 491 NM from City 03 NW Instr Approach **PRECISION**

Owner/Manager

Owner STEWART INT'L AIRPORT ACQUI

Manager MR CHARLES SELIGA

1035 FIRST STREET

NEW WINDSOR NY 12553

Phone (845) 564-2100 Fax

(845) 567-0532

E-mail MD@stewartintlairport.com Web site www.stewartintlairport.com

Services

Fuel JETA 100LL Airframe Repairs **MAJOR** Engine **MAJOR**

Attended ALL/ALL/ALL

Airline Airport YES

Transportation TAXI; LIMO; COURTESY VAN

Food ON AIRPORT Lodging OFF - 3 MILES

FBO (Location)

CAS


(845) 567-9210

RIFTON AVIATION SERVICES (S-TWYC)

(845) 567-9800 Freg 129.75 http://www.RiftonAviation.com/

Remarks

BIRDS AND DEER ON & INVOF ARPT. FBO/GA RAMP SOUTH OF RW 9/27 IS WITHIN FAR PART 107 RESTRICTED AREA AND PILOTS MAY BE REQUIRED TO PRODUCE VALID IDENTIFICATION. NOISE ABATEMENT PROCEDURES IN EFFECT, CONTACT AMGR. FEE FOR ACFT OVER 10000 LBS AND FOR ALL INTL FLIGHTS



Taxi Diagram